

XEBRID[™] 1-C10-G10

10% carbon fiber and 10% glass fiber reinforced PA66

| Physical Properties | Test Condition | Standard | Unit | Dam / Cond. |
|---|---------------------|-----------|---------------------|-------------|
| Density | | ISO 1183 | g/cm ³ | 1,25 |
| Water absorption (Equilibrium value) | 23 °C ; 50 % RH | | % | |
| Water absorption (Saturation value) | 23 °C ; water | | % | |
| Post-shrinkage | | | | |
| Parallel | | ISO 294-4 | % | |
| Normal | | ISO 294-4 | % | |
| Mechanical Properties | | | | |
| Tensile Modulus | 1 mm/min | ISO 527 | MPa | 12200 |
| Tensile Strength at break | 5 mm/min | ISO 527 | MPa | 190 |
| Tensile Elongation at break | 5 mm/min | ISO 527 | % | 2,2 |
| Flexural Modulus | 2 mm/min | ISO 178 | MPa | 9700 |
| Flexural Strength | 2 mm/min | ISO 178 | MPa | 270 |
| Flexural Stress at 3,5% strain | 2 mm/min | ISO 178 | MPa | |
| Flexural Strain at break | 2 mm/min | ISO 178 | % | 3,3 |
| Deflection at break | | | mm | |
| Deflection at 3,5% strain | | | mm | |
| Notched Izod Impact Strength | 23 °C ; 50 % RH | ISO 180 | kJ/m² | 6 |
| Unnotched Izod Impact Strength | 23 °C ; 50 % RH | ISO 180 | kJ/m² | 40 |
| Notched Izod Impact Strength | -30 °C | ISO 180 | kJ/m² | 5 |
| Unnotched Izod Impact Strength | -30 °C | ISO 180 | kJ/m² | 33 |
| Thermal Properties | | | | |
| Melting Point | 10 °C/min | ISO 11357 | °C | |
| HDT – heat deflection temperature | 0,45 MPa a 120 °C/h | ISO 75 | °C | |
| HDT – heat deflection temperature | 1,80 MPa a 120 °C/h | ISO 75 | °C | |
| HDT – heat deflection temperature | 8.00 MPa a 120 °C/h | ISO 75 | °C | 190 |
| VICAT - softening temperature | 10 N a 120 °C/h | ISO 306 | °C | |
| VICAT - softening temperature | 50 N a 120 °C/h | ISO 306 | °C | 250 |
| Coefficient of linear thermal expansion | | | | |
| 30÷50°C Parallel | | | 10 ⁻⁴ /K | |
| 30÷50°C Normal | | | 10 ⁻⁴ /K | |
| Maximum Usage Temperature | | | | |
| Short Term | | | °C | |
| Long Term | | | °C | |
| Electrical Properties | | | | |
| Volume Resistivity | | IEC 60093 | Ohm*m | 1E-01 |
| | | IEC 60093 | Ohm | 1E+05 |



XEBRID[™] 1-C10-G10

10% carbon fiber and 10% glass fiber reinforced PA66

| Process Recommendation | Test Condition | Standard | Unit | Value |
|------------------------|-----------------|----------|------|---------|
| Drying temperature | desiccant dryer | | °C | 80–100 |
| Drying time | desiccant dryer | | h | 6–8 |
| Melt temperature | | | °C | 260–270 |
| Mould temperature | | | °C | 85 |

Our advice does not release you from the obligation to verify the information currently provided - especially that contained in our safety data and technical information sheets, and to test our products as to their suitability for the intended processes and uses. The application, use and processing of our products and the products manufactured by you on the basis of our technical advice are beyond our control and, therefore, entirely your own responsibility. Our products are sold in accordance with the current version of our General Conditions of Sale and Delivery.

Test values

Unless specified to the contrary, the values given have been established on standardized test specimens at room temperature. The figures should be regarded as guide values only and not as binding minimum values. Kindly note that, under certain conditions, the properties can be affected to a considerable extent by the design of the mould/die, the processing conditions and the coloring.

Processing note

Under the recommended processing condition small quantities of decomposition product may be given off during processing. To preclude any risk to the health and well-being of the machine operatives, tolerance limits for the work environment must be ensured by the provision of efficient exhaust ventilation and fresh air at the workplace in accordance with the Safety Data Sheet. In order to prevent the partial decomposition of the polymer and the generation of volatile decomposition products, the prescribed processing temperatures should not be substantially exceeded. Since excessively high temperatures are generally the result of operator error or defects in the heating system, special care and controls are essential in these areas.

Edition: June 2022